Cleaning the LED Head

Clean the LED head if vertical white lines appear, images are faded, or the periphery of letters are smudged in the printouts.

Note

- Do not use solvents, such as methyl alcohol or thinners, because they may damage the LED head.

- Do not expose the image drum to direct sunlight or strong light (approximately 1,500 lux or more). Even under room lighting, do not leave the image drum for 5 minutes or more.

1. **Hold the handle (A) to open the scanner unit.**

2. **Insert your finger into the lever (B) on the right side of the machine and pull the front cover open lever (1) to open the front cover (2) forward.**


3. **Press the button (C) and open the Output Tray (3).**

| **Possible to get burned.** |
| --- |
| The fuser unit is extremely hot. Do not touch it. |

4. Wipe the four lenses of the LED heads with a soft tissue paper lightly.

5. Close the Output Tray by pushing the both sides of the Output Tray firmly.

6. **Close the front cover.**

Note

The front cover cannot be closed if the Output Tray is not closed securely.

7. **Hold the handle (A) to close the scanner unit.**